2007 Mercedes-Benz CL600 V-12 TT

Cars & Trucks | Condition Score Estimate: 80% (Illustrative)

VIN WDDEJ76X27A004478	**Mileage** 59 mi	
Prepared by Pro Auto Sales LLC	**Condition Score Estimate** 80% — Fair (Estimated)	**Rating basis** 66 estimated ratings

Review date: Nov 29, 2026

Illustrative auto-generated estimate: The score is calculated from all 66 auto-assigned illustrative ratings: Excellent=100, Good=88, Fair=72. Every individual rating is estimated, NOT the result of a verified physical inspection, title check or mechanical test.

Documentation & History

Ownership/title documents reviewed	**GOOD (EST.)**
Service and maintenance records reviewed	**GOOD (EST.)**
Vehicle history report reviewed	**GOOD (EST.)**
Odometer documentation compared	**GOOD (EST.)**
Lien/encumbrance documents reviewed	**GOOD (EST.)**

Exterior & Body

Body panels and alignment	**FAIR (EST.)**
Paint and finish	**FAIR (EST.)**
Exterior glass and mirrors	**FAIR (EST.)**
Doors, hood and closures	**FAIR (EST.)**
Visible corrosion and rust	**FAIR (EST.)**
Undercarriage visible condition	**FAIR (EST.)**

Interior & Cabin

Seat upholstery and adjustment	**FAIR (EST.)**
Dashboard and instrument displays	**FAIR (EST.)**
Interior trim and controls	**FAIR (EST.)**
Windows, mirrors and locks	**FAIR (EST.)**
Seat belts and cabin safety	**FAIR (EST.)**

Engine

Engine starting and idle	**FAIR (EST.)**
Engine leaks/visual check	**GOOD (EST.)**
Cooling system	**FAIR (EST.)**
Belts and hoses	**GOOD (EST.)**
Engine warning indicators	**GOOD (EST.)**
Abnormal sound or smoke	**GOOD (EST.)**

Transmission & Drivetrain

Gear engagement and shifting	**EXCELLENT (EST.)**
Transmission fluid/leaks	**GOOD (EST.)**
Driveshafts and joints	**GOOD (EST.)**
Differentials and axles	**FAIR (EST.)**

Brakes

Service brake operation	**GOOD (EST.)**
Parking brake operation	**GOOD (EST.)**
Brake lines and hoses	**GOOD (EST.)**
Rotor/drum and pad condition	**GOOD (EST.)**

Suspension & Steering

Steering play and responsiveness	**GOOD (EST.)**
Springs and mounts	**GOOD (EST.)**
Shocks and struts	**GOOD (EST.)**
Bushings and ball joints	**FAIR (EST.)**

Wheels & Tires

Tread depth and wear	**FAIR (EST.)**
Tire sidewalls and pressure	**FAIR (EST.)**
Wheel condition	**FAIR (EST.)**
Spare wheel and tools	**FAIR (EST.)**

Electrical & Lighting

Battery and charging	**GOOD (EST.)**

Exterior lights	**FAIR (EST.)**
Signals and hazard lights	**GOOD (EST.)**
Wipers and washers	**GOOD (EST.)**
Infotainment and accessories	**GOOD (EST.)**

Climate & HVAC

Air-conditioning operation	**FAIR (EST.)**
Heating operation	**FAIR (EST.)**
Ventilation and controls	**FAIR (EST.)**

Safety Systems

Airbag/SRS indicator	**GOOD (EST.)**
ABS indicator	**GOOD (EST.)**
Safety belts	**FAIR (EST.)**
Horn operation	**GOOD (EST.)**

Road Test

Acceleration and engine response	**FAIR (EST.)**
Steering while moving	**GOOD (EST.)**
Braking while moving	**GOOD (EST.)**
Transmission while moving	**GOOD (EST.)**
Unusual vibration or noises	**FAIR (EST.)**

Frame & Structure

Frame and mounting points	**FAIR (EST.)**
Visible structural repair	**GOOD (EST.)**
Body mounting areas	**FAIR (EST.)**
Suspension mounts	**GOOD (EST.)**

Service & Fluids

Engine oil level/condition	**GOOD (EST.)**
Coolant level/condition	**FAIR (EST.)**
Brake fluid	**GOOD (EST.)**

Other accessible fluids	**GOOD (EST.)**

Equipment & Other

Equipment operation where fitted	**FAIR (EST.)**
Warning codes if scanned	**FAIR (EST.)**
Additional fitted systems	**FAIR (EST.)**

Prepared by Pro Auto Sales LLC. Auto-generated estimated checklist ratings are illustrative, not recorded inspection findings. Independent buyer verification is recommended.