# 2026 Hyundai Elantra SE

Cars & Trucks | Condition Score Estimate: 93% (Illustrative)

| | | |
|---|---|---|
| **VIN**<br>KMHLL4DG8TU200863 | **Mileage**<br>6 mi | |
| **Prepared by**<br>Pro Auto Sales LLC | **Condition Score Estimate**<br>93% — Excellent (Estimated) | **Rating basis**<br>66 estimated ratings |

**Review date:** Nov 29, 2026

**Illustrative auto-generated estimate:** The score is calculated from all 66 auto-assigned illustrative ratings: Excellent=100, Good=88, Fair=72. Every individual rating is estimated, NOT the result of a verified physical inspection, title check or mechanical test.

## Documentation & History

| | |
|---|---|
| Ownership/title documents reviewed | **EXCELLENT (EST.)** |
| Service and maintenance records reviewed | **EXCELLENT (EST.)** |
| Vehicle history report reviewed | **EXCELLENT (EST.)** |
| Odometer documentation compared | **EXCELLENT (EST.)** |
| Lien/encumbrance documents reviewed | **EXCELLENT (EST.)** |

## Exterior & Body

| | |
|---|---|
| Body panels and alignment | **FAIR (EST.)** |
| Paint and finish | **GOOD (EST.)** |
| Exterior glass and mirrors | **FAIR (EST.)** |
| Doors, hood and closures | **FAIR (EST.)** |
| Visible corrosion and rust | **GOOD (EST.)** |
| Undercarriage visible condition | **GOOD (EST.)** |

## Interior & Cabin

| | |
|---|---|
| Seat upholstery and adjustment | **FAIR (EST.)** |
| Dashboard and instrument displays | **GOOD (EST.)** |
| Interior trim and controls | **GOOD (EST.)** |
| Windows, mirrors and locks | **GOOD (EST.)** |
| Seat belts and cabin safety | **FAIR (EST.)** |

## Engine

| | |
|---|---|
| Engine starting and idle | **GOOD (EST.)** |
| Engine leaks/visual check | **EXCELLENT (EST.)** |
| Cooling system | **EXCELLENT (EST.)** |
| Belts and hoses | **EXCELLENT (EST.)** |
| Engine warning indicators | **EXCELLENT (EST.)** |
| Abnormal sound or smoke | **EXCELLENT (EST.)** |

## Transmission & Drivetrain

| | |
|---|---|
| Gear engagement and shifting | **EXCELLENT (EST.)** |
| Transmission fluid/leaks | **EXCELLENT (EST.)** |
| Driveshafts and joints | **EXCELLENT (EST.)** |
| Differentials and axles | **EXCELLENT (EST.)** |

## Brakes

| | |
|---|---|
| Service brake operation | **EXCELLENT (EST.)** |
| Parking brake operation | **EXCELLENT (EST.)** |
| Brake lines and hoses | **EXCELLENT (EST.)** |
| Rotor/drum and pad condition | **EXCELLENT (EST.)** |

## Suspension & Steering

| | |
|---|---|
| Steering play and responsiveness | **EXCELLENT (EST.)** |
| Springs and mounts | **EXCELLENT (EST.)** |
| Shocks and struts | **EXCELLENT (EST.)** |
| Bushings and ball joints | **EXCELLENT (EST.)** |

## Wheels & Tires

| | |
|---|---|
| Tread depth and wear | **GOOD (EST.)** |
| Tire sidewalls and pressure | **GOOD (EST.)** |
| Wheel condition | **GOOD (EST.)** |
| Spare wheel and tools | **FAIR (EST.)** |

## Electrical & Lighting

| | |
|---|---|
| Battery and charging | **EXCELLENT (EST.)** |

| | |
|---|---|
| Exterior lights | **EXCELLENT (EST.)** |
| Signals and hazard lights | **EXCELLENT (EST.)** |
| Wipers and washers | **EXCELLENT (EST.)** |
| Infotainment and accessories | **EXCELLENT (EST.)** |

## Climate & HVAC

| | |
|---|---|
| Air-conditioning operation | **FAIR (EST.)** |
| Heating operation | **FAIR (EST.)** |
| Ventilation and controls | **FAIR (EST.)** |

## Safety Systems

| | |
|---|---|
| Airbag/SRS indicator | **EXCELLENT (EST.)** |
| ABS indicator | **EXCELLENT (EST.)** |
| Safety belts | **EXCELLENT (EST.)** |
| Horn operation | **EXCELLENT (EST.)** |

## Road Test

| | |
|---|---|
| Acceleration and engine response | **EXCELLENT (EST.)** |
| Steering while moving | **EXCELLENT (EST.)** |
| Braking while moving | **EXCELLENT (EST.)** |
| Transmission while moving | **EXCELLENT (EST.)** |
| Unusual vibration or noises | **EXCELLENT (EST.)** |

## Frame & Structure

| | |
|---|---|
| Frame and mounting points | **EXCELLENT (EST.)** |
| Visible structural repair | **EXCELLENT (EST.)** |
| Body mounting areas | **EXCELLENT (EST.)** |
| Suspension mounts | **EXCELLENT (EST.)** |

## Service & Fluids

| | |
|---|---|
| Engine oil level/condition | **EXCELLENT (EST.)** |
| Coolant level/condition | **EXCELLENT (EST.)** |
| Brake fluid | **EXCELLENT (EST.)** |

| | |
|---|---|
| Other accessible fluids | **EXCELLENT (EST.)** |

## Equipment & Other

| | |
|---|---|
| Equipment operation where fitted | **FAIR (EST.)** |
| Warning codes if scanned | **FAIR (EST.)** |
| Additional fitted systems | **FAIR (EST.)** |

Prepared by Pro Auto Sales LLC. Auto-generated estimated checklist ratings are illustrative, not recorded inspection findings. Independent buyer verification is recommended.